

**Daftar Lelang Floor Mobil - SIDOARJO | 01/07/2026 ( 340 )**  
**KOTA SIDOARJO (SDA) / JI. PANGLIMA SUDIRMAN NO.17 B, MENYANGGONG, KLETEK, KEC TAMAN, KAB SIDOARJO, JAWA , 61257**

**KATALOG INI HANYA SEBAGAI PANDUAN SAJA. BUKAN SEBAGAI PEDOMAN ATAU SEBAGAI BAHAN ACUAN COMPLAIN**

SmartBID melelang unit apa adanya, peserta lelang wajib melakukan cek fisik kendaraan dan dokumen dengan sebaik-baiknya. Pemenang lelang telah dianggap sudah memahami kondisi dan dokumen kendaraan yang telah dimenangkan. Deposit dan pelunasan unit Lelang SmartBID hanya melalui transfer Bank Central Asia, Tbk (BCA) a/n PT. Anugerah Lelang Indonesia, nomor rekening : 4688897988 (Sidoarjo), 4686088588 (Semarang), 4687088688 (Tangerang), 4688670088 (Makassar) .

**Note:**  
 Setiap unit dikenakan biaya administrasi sebesar: **Rp. 3.500.000,-**  
 Khusus untuk unit dengan harga terbentuk di atas **Rp. 350.000.000,-** dikenakan admin fee 1% dari harga terbentuk.

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
1	L 1865 DF	mitsubishi 1.2L GLS	2015	AT	1193	PUTIH MUTIARA	RP61.000.000	BENSIN	110353	C	C	D	14 HARI KERJA	ADA 2021-07-23	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC FIRMAN 62 812-3674-7297 / CHANDRA 0878-6190-3208 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS															KEUR T/A	SPH T/A	FORM A T/A
2	DT 8634 DH	MITSUBISHI FE 75	2023	MT	3907	KUNING	RP167.000.000	SOLAR	0	E	E	F	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC ARDIAZ 082142028080 // // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS															KEUR T/A	SPH T/A	FORM A T/A
3	DH 1554 CE	SUZUKI ALL NEW ERTIGA GA	2023	MT	1462	PUTIH METALIK	RP121.000.000	BENSIN	92289	B	B	B	READY	ADA 2026-09-18	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
BPKB READY DI HO TANGERANG // SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC BOY +62 821-8725-3174 // // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS															KEUR T/A	SPH T/A	FORM A T/A
4	DH 1160 CD	SUZUKI ERTIGA GL	2022	MT	1462	ABU ABU METALIK	RP90.000.000	BENSIN	0	D	D	E	14 HARI KERJA	ADA 2026-03-02	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC PAK NATAN 081338280981 / INSPEKSI PAK GAD 085338212232 // // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS															KEUR T/A	SPH T/A	FORM A T/A
5	B 9752 SCM	DAIHATSU GRAN MAX	2022	MT	1298	HITAM	RP108.000.000	BENSIN	118319	D	C	D	15 HARI KERJA	ADA 2026-01-09	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC FIRMAN 62 812-3674-7297 / CHANDRA 0878-6190-3208 / UNIT DIKENAKAN BIAYA PPN 1.1% DARI HARGA TERBENTUK // // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS															KEUR T/A	SPH T/A	FORM A T/A
6	PB 8957 M	MITSUBISHI TRITON DC EXCEED (4X4)	2016	MT	2477	MERAH SOLID	RP77.000.000	SOLAR	0	-	-	-	14 HARI KERJA	ADA 2026-05-10	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
NOPOL FISIK T/A // ADA PERBEDAAN JENIS KENDARAAN PADA FISIK DAN BPKB DOUBLE CABIN PADA STNK & NOTICE PICKUP // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC BPK. IMMANUEL 0822-3903-7374 / CS PUSAT 081188089292// BODY BARET PENYOK, MESIN RUSAK (TURUN MESIN), BUMPE T/A, KACA PECAH, INTERIOR KUSAM, BAN DAN VELG IMITASI, CAT KUSAM DEMPULAN, BAK PENYOK, AS RODA RUSAK, JOK SOBEK, MESIN REMBES, LAMPU KUSAM, TIRE (FR-L)   GASKET COVER HEAD   RADIATOR FAN   BRAKE MASTER   TIRE (RR-L)   ENGINE SERVICES (HEAVY)   GASKET CYLINDER HEAD   COIL IGNITION   AIRCON EVAPORATOR   WHEEL BEARING (RR)   TIRE (FR-R)   RIM (RR-R)   SPRING (RR)   FUEL PUMP   CEK ENGINE LIGHT   RIM (SPARE)   AIR FILTER   DINAMO STARTER   TURBO   HEADER   RIM (FR-L)   TIRE (SPARE)   DYNAMO STARTER   INJECTOR   RIM (FR-R)   TIRE (RR-R)   WHEEL BEARING (FR)   BRAKE PAD (RR)   DISC PAD   FAN BELT   RADIATOR   BRAKE PAD (FR)   SPRING (FR)   RACK STEER   SHOCBREAKERS (RR)   WHEEL AXELS (RR)   ENGINE MOUNTING   SHOCBREAKERS (FR)   RIM (RR-L)   CLUTCH PLATE   WHEEL AXELS (FR)   BATTERY   SPARK PLUG(S)/BOLT CRANE AND JACK   INTERIOR SALOON   TOOL KIT   CARSEAT (FR-R)   CARPET   CARSEAT (FR-L)   HEAD UNIT/FOG LAMP (L)   WINDSHIELD GLASS   LICENSE PLAT   DOOR REPAIR (RR-L)   TAILLIGHT (RR-L)   TURN LAMP (RR-R)   FOG LAMP (R)   TURN LAMP (FR-R)   TAILLIGHT (RR-R)   TURN LAMP (RR-L)   FENDER REPAIR (FR-L)   HEADLIGHT (FR-L)   CARGO PANEL REPAIR (RR)   HEADLIGHT (FR-R)   TURN LAMP (FR-L)   ROOF REPAIR   DOOR REPAIR (FR-L)   DOOR REPAIR (RR-R)   BUMPER REPLACE (FR)   DOOR REPAIR (FR-R)   FENDER REPAIR (FR-R) // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS															KEUR T/A	SPH T/A	FORM A T/A
7	PB 1534 D	TOYOTA RUSH G	2021	MT	1496	HITAM METALIK	RP136.000.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2024-12-01	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELengkapan DOKUMEN		
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. IMMANUEL 0822-3903-7374 / CS PUSAT 081188089292// UNIT LAKA, MESIN MATI, BAGIAN DEPAN RUSAK, APRON DAN BULLHEAD BENGKOK, BUMPER RUSAK, GRILL RUSAK, INTERIOR KOTOR, PLAFON IMITASI, SARUNG JOK IMITASI, LAMPU PECAH, RADIATOR RUSAK, CHASIS DEPAN BENGKOK, KAP MESIN PENYOK, KARPET TIDAK LENGKAP./ENGINE MOUNTING   GASKET CYLINDER HEAD   L-APRON   INJECTOR   HEADER   BRAKE PAD (RR)   CLUTCH PLATE   AIRCON EVAPORATOR   COIL IGNITION   GASKET COVER HEAD   SPRING (FR)   FUEL PUMP   SPRING (RR)   ENGINE SERVICES (HEAVY)   BATTERY   WHEEL BEARING (RR)   FR-APRON   TIRE (FR-R)   DISC PAD   TIRE (RR-R)   TIRE (SPARE)   TIRE (FR-L)   CLUTCH BEARING   SPARK PLUG(S)   FAN BELT   SHOCBREAKERS (RR)   BRAKE PAD (FR)   WHEEL BEARING (FR)   TIRE (RR-L)   BRAKE MASTER   SHOCBREAKERS (FR)   RADIATOR FAN   RADIATOR   RACK STEER/CARSEAT (RR-R)   CARSEAT (M-R)   CARSEAT (M-L)   CARSEAT (RR-L)   BOLT CRANE AND JACK   CARPET   CARPET FLOOR (RR)   CARPET FLOOR (MID)   INTERIOR SALOON   CARPET FLOOR (FR-R)   CARSEAT (FR-L)   HEAD UNIT   TOOL KIT   CARPET FLOOR (FR-L)   CEILING TRIM/ENGINE HOOD REPLACE   BUMPER REPLACE (FR)   TAILLIGHT (RR-L)   DOOR REPAIR (RR-R)   GRILLES   ROOF REPAIR   EMBLEM   WINDSHIELD GLASS   TAILLIGHT (RR-R)   FENDER REPLACE (FR-R)   FENDER REPLACE (FR-L)   TURN LAMP (RR-L)   LICENSE PLATE   HEADLIGHT (FR-R)   DOOR REPAIR (RR-L)   FOG LAMP (R)   TURN LAMP (FR-R)   HEADLIGHT (FR-L)   TURN LAMP (FR-L)   BUMPER REPAIR (RR)   DOOR REPAIR (FR-R)   TURN LAMP (RR-R)   FOG LAMP (L)   DOOR REPAIR (TRUNK)   DOOR REPAIR (FR-L) // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
8	DD 1719 BL	DAIHATSU XENIA R	2016	MT	1329	ABU ABU METALIK	RP47.000.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2026-11-12	KWT. BLANKO T/A KEUR T/A	FAKTUR ADA SPH T/A	FC. KTP T/A FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. REZA 0813-4377-9338 / CS PUSAT 081188089292 // UNIT LAKA LANTAS, BULLHEAD PENYOK, CHASIS DEPAN PENYOK, AS RODA RUSAK, SETIR IMITASI, KACA DEPAN PECAH, AIRBAG PECAH, APRON KANAN KIRI PENYOK, KOMPONEN MESIN TIDAK LENGKAP, KAP MESIN TERLEPAS, JOK BARIS 3 T/A, DOORTRIM T/A, MESIN REMBES OLI, SPARKBOARD T/A, VELG DEPAN IMITASI//ENGINE SERVICES (HEAVY)   TIRE (RR-L)   FR-APRON   AIRBAG SENSOR   TIRE (RR-R)   RIM (SPARE)   TIRE (FR-L)   SPRING (FR)   RIM (FR-R)   SPARE KEY (IMMOBILIZER)   SPRING (RR)   RACK STEER   TIRE (FR-R)   L-APRON   FAN BELT   TIRE (SPARE)   R-APRON   RIM (FR-L)   AIRBAG   WHEEL AXELS (FR)   CLUTCH PLATE   BRAKE PAD (RR)   WHEEL AXELS (RR)   INJECTOR   CLUTCH BEARING   BATTERY   ENGINE MOUNTING   SPARK PLUG(S)   BRAKE PAD (FR)   AIRCON EVAPORATOR   RADIATOR   RADIATOR FAN   BRAKE MASTER/FR-DOOR (MID)   TOOL KIT   HEADREST (RR-L)   DOOR TRIM (TRUNK)   DOOR TRIM (FR-R)   INTERIOR SALOON   CARPET   HORN   CEILING LAMP (FR)   INTERIOR MIRROR   BOLT CRANE AND JACK   CARPET FLOOR (RR)   DOOR TRIM (RR-L)   CARPET FLOOR (FR-R)   CARPET FLOOR (FR-L)   CEILING TRIM   DOOR TRIM (RR-R)   CEILING LAMP (RR)   CARSEAT (RR-R)   DASHBOARD   HEADREST (RR-R)   AIRCON PANEL   CARSEAT (RR-L)   HEAD UNIT   DOOR TRIM (FR-L)   STEERING-WHEEL/GRILLES   ROOF REPAIR   WINDSHIELD WIPER   FOG LAMP (R)   TURN LAMP (RR-R)   RIM COVER (FR-L)   EX-ACCIDENT   TAILLIGHT (RR-L)   FENDER REPAIR (RR-R)   RIM COVER (RR-L)   ENGINE HOOD REPAIR   ANTENNA   TURN LAMP (FR-L)   SIDE SKIRT REPAIR (L)   FOG LAMP (L)   DOOR REPAIR (FR-R)   DOOR REPAIR (FR-R)   SIDE SKIRT REPAIR (R)   RIM COVER (FR-R)   DOOR REPAIR (RR-R)   LICENSE PLATE   FENDER REPAIR (RR-L)   TAILLIGHT (RR-R)   DOOR REPAIR (TRUNK)   TURN LAMP (RR-L)   DOOR REPAIR (FR-L)   TURN LAMP (FR-R)   EMBLEM   WINDSHIELD GLASS   RIM COVER (RR-R)   MIRROR (L)   FENDER REPLACE (FR-R)   MIRROR (R)   HEADLIGHT (FR-L)   FENDER REPLACE (FR-L)   BUMPER REPAIR (RR)   HEADLIGHT (FR-R)   BUMPER REPLACE (FR) // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
9	PA 8739 GZ	TOYOTA HILUX 2.5 E 4X4 DC	2014	MT	2494	PUTIH	RP64.000.000	SOLAR	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A KEUR T/A	FAKTUR T/A SPH T/A	FC. KTP T/A FORM A T/A
NOPOL FISIK T/A // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. RISON 0812-4751-9346 / CS PUSAT 081188089292// BODY BARET, BUMPER BARET, CAT KUSAM, MESIN MATI TERBURAI TIDAK LENGKAP, LAMPU KUSAM PECAH DAN TIDAK LENGKAP, FOOGLAMP T/A, PENNUTUP BAK IMITASI, VELG PENYOK DAN IMITASI, STIR RUSAK, HEAD UNIT T/A, INTERIOR KOTOR, AIRBAG T/A, BAN GUNDUL, TRANSMISI INDIKASI BONGKARAN, POWER WINDOW T/A./SHOCBREAKERS (FR)   ECU   TIRE (RR-L)   TIRE (SPARE)   BRAKE PAD (FR)   DYNAMO STARTER   GASKET CYLINDER HEAD   RADIATOR FAN   TIRE (RR-R)   GASKET COVER HEAD   RIM (SPARE)   POWER STEERING   TIRE (FR-R)   HEADER   FUEL PUMP   COIL IGNITION   DINAMO STARTER   SPRING (FR)   ENGINE MOUNTING   DISC PAD   AIRCON EVAPORATOR   RIM (RR-R)   SHOCBREAKERS (RR)   FAN BELT   AIRBAG   WHEEL BEARING (FR)   INJECTOR   SPARK PLUG(S)   TIRE (FR-L)   BRAKE PAD (RR)   SPRING (RR)   BRAKE MASTER   AIR FILTER   ENGINE BLOCK   RACK STEER   RIM (FR-L)   CLUTCH PLATE   WHEEL BEARING (RR)   RIM (FR-R)   RIM (RR-L)   RADIATOR   BATTERY/BOLT CRANE AND JACK   STEERING-WHEEL   HEAD UNIT   CARSEAT (FR-R)   POWER-WINDOW PANEL (FR-R)   CEILING TRIM   CARPET   INTERIOR SALOON   CARSEAT (FR-L)   TOOL KIT/RR-DOOR GLASS (R)   DOOR REPAIR (FR-R)   FOG LAMP (L)   TAILLIGHT (RR-L)   TURN LAMP (RR-L)   TAILLIGHT (RR-R)   FR-DOOR GLASS (L)   FR-DOOR GLASS (R)   ELECTRIC MIRROR (L)   TURN LAMP (RR-R)   CARGO PANEL REPAIR (RR)   FOG LAMP (R)   RR-DOOR GLASS (L)   ELECTRIC MIRROR (R)   ENGINE HOOD REPAIR   BUMPER REPAIR (FR)   TURN LAMP (FR-R)   HEADLIGHT (FR-R)   TURN LAMP (FR-L)   DOOR REPAIR (RR-R)   BUMPER REPAIR (RR)   DOOR REPAIR (RR-L)   HEADLIGHT (FR-L)   ROOF REPAIR   DOOR REPAIR (FR-L) // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
10	KT 1005 GJ	DAIHATSU AYL A 1.2X	2020	MT	1197	KUNING METALIK	RP85.000.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2025-12-21	KWT. BLANKO T/A KEUR T/A	FAKTUR ADA SPH T/A	FC. KTP T/A FORM A T/A
STNK HANYA FOTO SCAN // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT PIC BPK. MASSUARAH 0813-5561-8851 / HUBUNGI CS PUSAT 081188089292// MESIN BERFUNGSI, BODY TERGORES, HEAD UNIT T/A, ALAT MOBIL T/A, SARUNG JOK IMITASI, COVER PLAFON IMITASI, COVER TUAS TRANSMISI IMITASI//RIM (SPARE)   SPRING (FR)   BRAKE MASTER   SPRING (RR)   GASKET COVER HEAD   TIRE (SPARE)   SPARE KEY (IMMOBILIZER)   TIRE (RR-R)   ENGINE SERVICES (LIGHT)   CLUTCH PLATE   FAN BELT   BRAKE PAD (RR)   TIRE (FR-L)   AIRCON EVAPORATOR   SPARK PLUG(S)   BRAKE PAD (FR)   TIRE (FR-R)   BATTERY   GASKET CYLINDER HEAD   TIRE (RR-L)   CLUTCH BEARING   INJECTOR/CEILING TRIM   TOOL KIT   INTERIOR SALOON   HEAD UNIT   BOLT CRANE AND JACK   CARPET FLOOR (RR)   GEAR LEVER COVER/SIDE SKIRT REPAIR (R)   MIRROR (R)   SIDE SKIRT REPAIR (L)   TAILLIGHT (RR-R)   FENDER REPAIR (FR-L)   WINDSHIELD WIPER   MIRROR (R)   TAILLIGHT (RR-L)   EMBLEM   FENDER REPAIR (FR-R)   BUMPER REPAIR (FR)   FENDER REPAIR (RR-L)   BUMPER REPAIR (RR)   FENDER REPAIR (RR-R) // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
11	DC 1181 AU	TOYOTA AVANZA 1.3 E	2016	MT	1329	SILVER METALIK	RP96.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A KEUR T/A	FAKTUR ADA SPH T/A	FC. KTP T/A FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC BPK. PAUL 0823-1581-4593 / CS PUSAT 081188089292// MESIN BERFUNGSI, BODY TERGORES & PENYOK, ACCU SUAK, ALARM T/A, KLAKSON TIDAK BERFUNGSI, ALAT MOBIL T/A, HEADREST TIDAK LENGKAP, KACA DEPAN RETAK, COVER JOK IMITASI, MESIN REMBES OLI, BULLHEAD BERKARAT (REKONDISI), VELG IMITASI, KONDISI BAN GUNDUL, INDIKASI UNIT EX-LAKA DEPAN KANAN/SPARE KEY (IMMOBILIZER)   REMOTE   RADIATOR   TIRE (RR-L)   TIRE (FR-L)   TIRE (SPARE)   RIM (FR-L)   RIM (FR-R)   ENGINE SERVICES (LIGHT)   AIRCON EVAPORATOR   RADIATOR FAN   RIM (SPARE)   RIM (RR-L)   BRAKE PAD (FR)   BRAKE PAD (RR)   FR-APRON   SPARK PLUG(S)   BRAKE MASTER   TIRE (RR-R)   GASKET COVER HEAD   R-APRON   SPRING (RR)   CLUTCH BEARING   RACK STEER   FAN BELT   SPRING (FR)   GASKET CYLINDER HEAD   BATTERY   INJECTOR   CLUTCH PLATE   TIRE (FR-R)/CEILING LAMP (FR)   INTERIOR MIRROR   HEADREST (FR-R)   HEADREST (RR-L)   CEILING LAMP (RR)   CARPET FLOOR (RR)   CONSOLE BOX   CEILING TRIM   INTERIOR SALOON   CARPET FLOOR (FR-R)   TOOL KIT   HORN   CARPET FLOOR (MID)   HEADREST (RR-L)   CARPET   BOLT CRANE AND JACK   AIRCON PANEL   HEADREST (FR-L)   CARPET FLOOR (FR-L)/RIM COVER (FR-L)   TURN LAMP (RR-L)   WINDSHIELD GLASS   SIDE SKIRT REPAIR (L)   TURN LAMP (FR-L)   TAILLIGHT (RR-R)   HEADLIGHT (FR-R)   TURN LAMP (RR-R)   TAILLIGHT (RR-L)   RIM COVER (RR-L)   RIM COVER (FR-R)   HEADLIGHT (FR-L)   SIDE SKIRT REPAIR (R)   RIM COVER (RR-R)   ANTENNA   MIRROR (R)   DOOR REPAIR (FR-R)   MIRROR (L)   ENGINE HOOD REPAIR   WINDSHIELD WIPER   ROOF REPAIR   FENDER REPAIR (RR-R)   FENDER REPAIR (FR-R)   DOOR REPAIR (RR-R)   FENDER REPAIR (RR-L)   DOOR REPAIR (TRUNK)   DOOR REPAIR (FR-L)   FENDER REPAIR (FR-L)   EMBLEM   BUMPER REPAIR (RR)   DOOR REPAIR (RR-L)   BUMPER REPAIR (FR) // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
12	DD 1529 UE	TOYOTA INNOVA	2008	MT	1998	HITAM METALIK	RP56.000.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2026-01-06	KWT. BLANKO T/A KEUR T/A	FAKTUR ADA SPH T/A	FC. KTP T/A FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN						
KEUR T/A	SPH T/A	FORM A T/A	<p>FOTO NOKA &amp; NOSIN BERKARAT // PEMENANG LELANG WAJIB TTD SURAT PERNYATAAN DIATAS MATERAI // STNK HANYA FOTO SCAN // NOPOL FISIK T/A // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC BPK. PAUL 0823-1581-4593 / CS PUSAT 081188089292//UNIT LAKA LANTAS, BULLHEAD PENYOK, NOMOR RANGKA BERKARAT, CHASIS PENYOK, MESIN TIDAK BERFUNGSI, BAN CADANGAN T/A, HEAD UNIT T/A, ALAT MOBIL T/A, SPOILER T/A, KACA SPION T/A, BUMPER DEPAN T/A &amp; BUMPER BELAKANG RUSAK (TERLEPAS), HEADREST T/A, SEATBELT TIDAK LENGKAP//RADIATOR FAN   CLUTCH PLATE   FR-APRON   RIM (RR-R)   CHASSIS   RADIATOR   BRAKE PAD (FR)   CLUTCH BEARING   BRAKE PAD (RR)   TIRE (FR-R)   SPRING (RR)   BATTERY   GASKET COVER HEAD   SPRING (FR)   ENGINE SERVICES (LIGHT)   TIRE (SPARE)   BRAKE MASTER   RIM (SPARE)   FAN BELT   TIRE (FR-L)   TIRE (RR-L)   RACK STEER   SPARK PLUG(S)   GASKET CYLINDER HEAD   TIRE (RR-R)   AIRCON EVAPORATOR   INJECTOR   RIM (RR-L)/HEADREST (RR-R)   HEADREST (M-L)   HEADREST (FR-R)   SUNVISOR L   CARPET FLOOR (MID)   HEAD UNIT   AIRCON PANEL   HEADREST (M-R)   BOLT CRANE AND JACK   SUNVISOR R   INTERIOR MIRROR   SEATBELT (RR-L)   CEILING LAMP (RR)   HEADREST (RR-L)   HEADREST (FR-L)   DASHBOARD   INTERIOR SALOON   TOOL KIT   CEILING LAMP (FR)   CARPET FLOOR (FR-R)   CARPET FLOOR (FR-L)   CARPET   CARPET FLOOR (RR)   CEILING TRIM   SEATBELT (RR-R)/FENDER REPAIR (RR-L)   RIM COVER (RR-R)   DOOR REPAIR (RR-R)   ANTENNA   WINDSHIELD WIPER   HEADLIGHT (FR-R)   LICENSE PLATE   FOG LAMP (L)   TAILLIGHT (RR-R)   TURN LAMP (FR-R)   SIDE SKIRT REPAIR (L)   ENGINE HOOD REPLACE   ELECTRIC MIRROR (R)   BUMPER REPLACE (RR)   MIRROR (R)   DOOR REPAIR (FR-L)   FENDER REPLACE (FR-R)   RIM COVER (FR-R)   DOOR REPAIR (RR-L)   HEADLIGHT (FR-L)   RIM COVER (RR-L)   SPOILER (RR)   RIM COVER (FR-L)   DOOR REPAIR (FR-R)   ROOF REPAIR   EMBLEM   TURN LAMP (RR-L)   BUMPER REPLACE (FR)   ELECTRIC MIRROR (L)   SIDE SKIRT REPAIR (R)   FENDER REPLACE (FR-L)   TURN LAMP (RR-R)   FOG LAMP (R)   MIRROR (L)   TURN LAMP (FR-L)   DOOR REPAIR (TRUNK)   GRILLES   TAILLIGHT (RR-L)   FENDER REPAIR (RR-R) // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS</p>																		
13	PA 1784 GW	DAIHATSU TERIOS X	2022	MT	1496	SILVER METALIK	RP106.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	<table border="1"> <tr> <td>KWT. BLANKO T/A</td> <td>FAKTUR ADA</td> <td>FC. KTP T/A</td> </tr> <tr> <td>KEUR T/A</td> <td>SPH T/A</td> <td>FORM A T/A</td> </tr> </table>	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A	KEUR T/A	SPH T/A	FORM A T/A
KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A																			
KEUR T/A	SPH T/A	FORM A T/A																			
<p>NOPOL PADA FISIK T/A // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. RISON 0812-4751-9346 / CS PUSAT 081188089292// KONDISI UNIT LAKA LANTAS, RUSAK BAGIAN DEPAN, CHASIS BULLHEAD KAPMESIN BENGKOK PENYOK, LAMPU RUSAK KUSAM PECAH, BUMPER RUSAK, KACA PECAH, BUMPER BLAKANG T/A, KACA PECAH, MESIN MUNDUR, INTERIOR KUSAM, CHASIS PENYOK DEPAN./CHASSIS   WHEEL AXELS (FR)   ABS INDIKATOR   ABS INDIKATOR   DYNAMO STARTER   FUEL PUMP   SPRING (FR)   RIM (FR-R)   FR-APRON   GASKET CYLINDER HEAD   TIRE (RR-L)   WHEEL BEARING (RR)   FAN BELT   TIRE (RR-R)   INJECTOR   SPARK PLUG(S)   TIRE (SPARE)   R-APRON   BRAKE PAD (RR)   RIM (RR-L)   SHOCBREAKERS (RR)   RIM (FR-L)   TIRE (FR-L)   CLUTCH BEARING   GEAR BOX OVERHAUL   SHOCBREAKERS (FR)   POWER STEERING   WHEEL AXELS (RR)   RADIATOR FAN   BRAKE MASTER   GASKET COVER HEAD   ENGINE MOUNTING   ENGINE SERVICES (HEAVY)   MUFFLER   AIRCON EVAPORATOR   HEADER   TIRE (FR-R)   COIL IGNITION   SPRING (RR)   RIM (SPARE)   RIM (RR-R)   BATTERY   L-APRON   WHEEL BEARING (FR)   RACK STEER   CLUTCH PLATE   DISC PAD   RADIATOR   BRAKE PAD (FR)/CARPET FLOOR (RR)   HEAD UNIT   CARPET   CARPET FLOOR (FR-R)   CARPET FLOOR (FR-L)   INTERIOR SALOON   CARPET FLOOR (MID)   TOOL KIT   BOLT CRANE AND JACK/FENDER REPLACE (FR-R)   FENDER REPLACE (RR-L)   ENGINE HOOD REPLACE   TURN LAMP (FR-L)   TURN LAMP (RR-R)   ROOF REPAIR   ELECTRIC MIRROR (R)   DOOR REPAIR (FR-R)   TURN LAMP (FR-R)   FR-DOOR GLASS (L)   HEADLIGHT (FR-R)   HEADLIGHT (FR-L)   FR-DOOR GLASS (R)   FOG LAMP (R)   TAILLIGHT (RR-L)   DOOR REPAIR (FR-L)   WINDSHIELD GLASS   TAILLIGHT (RR-R)   DOOR REPAIR (TRUNK)   ELECTRIC MIRROR (L)   FOG LAMP (L)   DOOR REPAIR (RR-L)   TURN LAMP (RR-L)   BUMPER REPLACE (FR)   DOOR REPAIR (RR-R)   BUMPER REPLACE (RR)   RR-VENT GLASS (L) // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS</p>																					
14	PB 8722 ML	SUZUKI MEGA CARRY PU	2016	MT	1493	HITAM	RP35.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	<table border="1"> <tr> <td>KWT. BLANKO T/A</td> <td>FAKTUR T/A</td> <td>FC. KTP T/A</td> </tr> <tr> <td>KEUR T/A</td> <td>SPH T/A</td> <td>FORM A T/A</td> </tr> </table>	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A	KEUR T/A	SPH T/A	FORM A T/A
KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A																			
KEUR T/A	SPH T/A	FORM A T/A																			
<p>NO MESIN FISIK RUSAK / T/A // PEMENANG LELANG WAJIB MENANDATANGANI SURAT PERNYATAAN BERMATERAI // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. IMMANUEL 0822-3903-7374 / CS PUSAT 081188089292// NOSIN UNIT T/A, BODY BARET, BUMPER BARET, KARPET T/A, CAT KUSAM, EXREPAINT, JOK SOBEK, INTERIOR KUSAM, LAMPU KUSAM, MESIN REMBES./BRAKE PAD (RR)   BRAKE PAD (FR)   GEAR BOX OVERHAUL   WHEEL BEARING (FR)   WHEEL BEARING (RR)   RIM (FR-R)   ENGINE SERVICES (HEAVY)   RIM (SPARE)   HEADER   SPRING (RR)   COIL IGNITION   SPRING (FR)   TIRE (RR-L)   TIRE (FR-L)   AIR FILTER   GASKET CYLINDER HEAD   FAN BELT   GASKET COVER HEAD   RIM (FR-L)   RIM (RR-R)   TIRE (RR-R)   TIRE (SPARE)   RIM (RR-L)   TIRE (FR-R)   RADIATOR FAN   SPARK PLUG(S)   RADIATOR   RACK STEER   BATTERY   CLUTCH PLATE/TOOL KIT   CARSEAT (FR-R)   BOLT CRANE AND JACK   CARPET   INTERIOR SALOON/HEADLIGHT (FR-R)   FRONT PANEL REPAIR   TURN LAMP (FR-R)   TAILLIGHT (RR-R)   TURN LAMP (RR-R)   FENDER REPAIR (FR-L)   TURN LAMP (FR-L)   HEADLIGHT (FR-L)   DOOR REPAIR (FR-R)   TURN LAMP (RR-L)   TAILLIGHT (RR-L)   BUMPER REPAIR (FR)   FENDER REPAIR (FR-R)   DOOR REPAIR (FR-L)   ROOF REPAIR   CARGO PANEL REPAIR (DECK) // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS</p>																					