

Daftar Lelang Floor Mobil - LELANG ONLINE VAGANZA TIMUR | 25/02/2026 (72)
KOTA LELANG ONLINE VAGANZA TIMUR (LOV) / -

KATALOG INI HANYA SEBAGAI PANDUAN SAJA. BUKAN SEBAGAI PEDOMAN ATAU SEBAGAI BAHAN ACUAN COMPLAIN

SmartBID melelang unit apa adanya, peserta lelang wajib melakukan cek fisik kendaraan dan dokumen dengan sebaik-baiknya. Pemenang lelang telah dianggap sudah memahami kondisi dan dokumen kendaraan yang telah dimenangkan. Deposit dan pelunasan unit Lelang SmartBID hanya melalui transfer Bank Central Asia, Tbk (BCA) a/n PT. Anugerah Lelang Indonesia, nomor rekening : 4688897988 (Sidoarjo), 4686088588 (Semarang), 4687088688 (Tangerang), 4688670088 (Makassar) .

Note:
Setiap unit dikenakan biaya administrasi sebesar: **Rp. 3.000.000,-**
Khusus untuk unit dengan harga terbentuk di atas Rp. 333.000.000,- dikenakan admin fee 1% dari harga terbentuk.

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
1	N 1518 KH	MITSUBISHI PAJERO SPORT 2.5 D EXCEED (4X2)	2012	AT	2477	ABU PERAK METALIK	RP172.000.000	SOLAR	151733	C	C	C	14 HARI KERJA	ADA 2025-05-20	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC TOYIB +62 813-3202-4730 // //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
2	W 1553 DM	DAIHATSU GRAN MAX	2013	MT	1298	SILVER METALIK	RP56.000.000	BENSIN	241145	C	C	C	14 HARI KERJA	ADA 2026-03-06	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC AWAL +62 895-3231-57272 / ANDRI 085136886212 // //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
3	KT 8442 YH	DAIHATSU GRAN MAX PICK-UP 1.3	2018	MT	1298	ABU ABU METALIK	RP35.000.000	BENSIN	0	D	D	E	14 HARI KERJA	ADA 2026-04-26	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC MIRZA : 0822-3357-3376 / PIC RESKI 0853-4884-2551 // //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
4	W 1658 CF	HONDA BRIO SATYA DD1 1.2 E	2016	MT	1198	ABU ABU BAJA METALIK	RP71.000.000	BENSIN	103621	C	C	C	14 HARI KERJA	ADA 2026-01-09	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC AWAL +62 895-3231-57272 / ANDRI 085136886212 //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
5	KT 8101 GJ	MITSUBISHI FE 74 HD 125 PS	2021	MT	3908	KUNING	RP202.000.000	SOLAR	0	E	E	E	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC JO CHRIS 0852-1132-8319// NOPOL FISIK T/A // //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
6	DD 1799 VE	TOYOTA CALYA 1.2 G A/T	2019	AT	1197	MERAH	RP27.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI PIC BPK. RISON 0812-4751-9346 / CS PUSAT 081188089292// KONDISI UNIT MESIN MATI, UNIT LAKA LANTAS, BODY DEPAN RUSAK, CHASIS BULLHEAD PENYOK, LAMPU PECAH, BUMPER RUSAK, KACA PECAH, KAP MESIN PENYOK, MESIN MIRING, AIRBAG PECAH, INTERIOR KOTOR, BAN GUNDUL, MESIN REMBES OLI, KARPET T/A.//ENGINE MOUNTING HEADER CLUTCH BEARING COIL IGNITION TIRE (SPARE) INJECTOR GASKET COVER HEAD SPRING (RR) TIRE (FR-L) FAN BELT TIRE (RR-L) TIRE (FR-R) DISC PAD AIRCON EVAPORATOR SPARK PLUG(S) SHOCBREAKERS (FR) WHEEL BEARING (FR) ENGINE SERVICES (HEAVY) R-APRON RACK STEER CLUTCH PLATE GASKET CYLINDER HEAD SHOCBREAKERS (RR) BATTERY WHEEL BEARING (RR) RADIATOR FAN RADIATOR L-APRON DYNAMO STARTER TIRE (RR-R) MUFFLER BRAKE PAD (FR) CHASSIS BRAKE MASTER FR-APRON SPRING (FR) FUEL PUMP BRAKE PAD (RR)/CARPET FLOOR (RR) CARPET FLOOR (FR-L) INTERIOR SALOON CARPET FLOOR (FR-R) CARPET FLOOR (MID) BOLT CRANE AND JACK TOOL KIT STEERING-WHEEL CARPET CARSEAT (FR-R)/DOOR REPAIR (FR-L) TURN LAMP (FR-R) ROOF REPAIR HEADLIGHT (FR-R) DOOR REPAIR (TRUNK) TURN LAMP (RR-R) ENGINE HOOD REPLACE TAILLIGHT (RR-L) TURN LAMP (FR-L) DOOR REPAIR (FR-R) DOOR REPAIR (RR-R) HEADLIGHT (FR-L) TAILLIGHT (RR-R) DOOR REPAIR (RR-L) BUMPER REPLACE (FR) FOG LAMP (R) BUMPER REPAIR (RR) GRILLES TURN LAMP (RR-L) FENDER REPAIR (FR-L) FOG LAMP (L) FENDER REPAIR (FR-R) WINDSHIELD GLASS //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
7	PA 1275 EK	TOYOTA INNOVA G	2011	MT	1998	SILVER METALIK	RP25.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
NOSIN PADA FISIK TEMPELAN / KETRIK ULANG // PEMENANG LELANG WAJIB MENANDATANGANI SURAT PERNYATAAN BERMATERAI // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. DEDY 0812-7358-6232 / CS PUSAT 081188089292// BODY BARET PENYOK, BUMPER BARET PECAH, MESIN MATI RUSAK, KACA BELAKANG PECAH, HEAD UNIT T/A, NOSIN TEMPELAN, UNIT PLAT KUNING, BUMPER PECAH, LAMPU PECAH, LAMPU BELAKANG T/A, BAN DAN VELG IMITASI, LACI DASHBOARD T/A, STIR RACING, SARUNG JOK IMITASI, PLAFON VARIASI, //ENGINE MOUNTING WHEEL AXELS (RR) WHEEL AXELS (FR) AIRCON EVAPORATOR TIRE (SPARE) RIM (FR-L) RADIATOR FAN RIM (SPARE) CLUTCH BEARING TIRE (RR-R) HEADER GEAR BOX OVERHAUL RIM (RR-R) FUEL PUMP GASKET CYLINDER HEAD SPRING (FR) BRAKE PAD (FR) DYNAMO STARTER RIM (RR-L) GASKET COVER HEAD COIL IGNITION BATTERY BRAKE MASTER RIM (FR-R) SHOCBREAKERS (FR) SPRING (RR) TIRE (FR-L) RACK STEER FAN BELT TIRE (FR-R) TIRE (RR-L) SPARK PLUG(S) BRAKE PAD (RR) RADIATOR SHOCBREAKERS (RR) DISC PAD INJECTOR CLUTCH PLATE WHEEL BEARING (RR) WHEEL BEARING (FR) ENGINE SERVICES (HEAVY)/CARPET FLOOR (RR) STEERING-WHEEL TOOL KIT CARPET FLOOR (FR-L) CARPET CARPET FLOOR (MID) CARSEAT (FR-L) CARPET FLOOR (FR-R) CEILING TRIM INTERIOR SALOON HEAD UNIT CARSEAT (FR-R) BOLT CRANE AND JACK/WINDSHIELD WIPER FENDER REPAIR (FR-R) FENDER REPAIR (FR-L) BACK GLASS HEADLIGHT (FR-R) DOOR REPAIR (TRUNK) DOOR REPAIR (RR-R) TAILLIGHT (RR-R) DOOR REPAIR (FR-R) TURN LAMP (FR-R) TURN LAMP (RR-R) DOOR REPAIR (RR-L) TURN LAMP (FR-L) ENGINE HOOD REPAIR LICENSE PLATE TAILLIGHT (RR-L) DOOR REPAIR (FR-L) FOG LAMP (L) BUMPER REPAIR (RR) TURN LAMP (RR-L) HEADLIGHT (FR-L) FOG LAMP (R) ROOF REPAIR BUMPER REPAIR (FR) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
8	DM 1699 AB	TOYOTA INNOVA 2.0 V	2010	MT	1998	SILVER METALIK	RP60.000.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2026-08-31	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
STNK HANYA BERUPA FOTO SCAN // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. MASSUARAH 0813-5561-8851 / CS PUSAT 081188089292// MESIN BERFUNGSI, BODY TERGORES (CAT ULANG), KACA DEPAN RETAK, BUMPER DEPAN PECAH, AC TIDAK DINGIN, BAN CADANGAN T/A, ALAT MOBIL T/A, VELG IMITASI, SETIR IMITASI, LACI DASHBOARD T/A, HEADREST TIDAK LENGKAP, MESIN REMBES OLI, JOK BARIS KETIGA T/A//MUFFLER ENGINE SERVICES (LIGHT) GASKET CYLINDER HEAD RADIATOR RADIATOR FAN FAN BELT INJECTOR SPRING (FR) RIM (FR-L) BRAKE PAD (RR) TIRE (RR-L) COIL IGNITION BRAKE PAD (FR) TIRE (FR-R) RIM (RR-R) TIRE (FR-L) TIRE (SPARE) RIM (SPARE) CLUTCH PLATE BATTERY GASKET COVER HEAD SPRING (RR) RIM (FR-R) SPARK PLUG(S) CLUTCH BEARING TIRE (RR-R) AIRCON EVAPORATOR RIM (RR-L) BRAKE MASTER/DOOR TRIM (TRUNK) TRUNK DOOR LOCK CEILING LAMP (FR) CARSEAT (RR-L) CEILING TRIM CEILING LAMP (RR) CARPET FLOOR (MID) HEADREST (RR-L) CARPET HEADREST (FR-R) HEADREST (FR-L) BOLT CRANE AND JACK INTERIOR SALOON AIRCON PANEL HEAD UNIT HEADREST (RR-R) TOOL KIT HORN CARPET FLOOR (FR-R) CARPET FLOOR (FR-L) DASHBOARD CARPET FLOOR (RR) STEERING-WHEEL CARSEAT (RR-R)/TURN LAMP (FR-L) RIM COVER (RR-R) RIM COVER (RR-L) RIM COVER (FR-L) RIM COVER (FR-L) TURN LAMP (FR-R) ROOF REPAIR TURN LAMP (RR-R) HEADLIGHT (FR-L) ENGINE HOOD REPAIR TURN LAMP (RR-L) TAILLIGHT (RR-R) TAILLIGHT (RR-L) ANTENNA SIDE SKIRT REPAIR (R) EMBLEM FOG LAMP (R) FENDER REPAIR (FR-L) MIRROR (R) RIM COVER (FR-R) WINDSHIELD GLASS WINDSHIELD WIPER FENDER REPAIR (RR-L) BUMPER REPLACE (FR) FENDER REPAIR (RR-R) BUMPER REPAIR (RR) FENDER REPAIR (FR-R) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
9	DG 1336 KB	TOYOTA AVANZA AVANZA E	2012	MT	1298	KUNING	RP25.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK FAHMI/BPK. USMAN 0821-8761-0965 / 0823-9133-7272 / CS PUSAT 081188089292// BODY BARET FULL STIKER, BODY KEROPOS, INDIKASI UNIT EX TAKSI, BUMPER BARET, LAMPU KUSAM PECAH, FOGLMP T/A, LANTAI KEROPOS, BAN GUNDUL, MESIN REMBES OLI (EX BONGKARAN), HEAD UNIT T/A, STIR RACING, JOK BELAKANG T/A, SPION PECAH, PLAFON IMITASI//FUEL PUMP ENGINE SERVICES (HEAVY) RIM (RR-R) COIL IGNITION HEADER GASKET CYLINDER HEAD RIM (RR-L) TIRE (RR-R) WHEEL AXELS (FR) GASKET COVER HEAD SPRING (FR) RIM (SPARE) SPRING (RR) WHEEL BEARING (RR) AIRCON EVAPORATOR RIM (FR-R) WHEEL AXELS (RR) SHOCBREAKERS (RR) ENGINE MOUNTING FAN BELT TIRE (FR-L) DISC PAD BRAKE PAD (RR) WHEEL BEARING (FR) TIRE (FR-R) CLUTCH BEARING RIM (FR-L) TIRE (RR-L) BATTERY RACK STEER TIRE (SPARE) RADIATOR FAN SHOCBREAKERS (FR) RADIATOR SPARK PLUG(S) INJECTOR CLUTCH PLATE BRAKE PAD (FR) BRAKE MASTER/STEERING-WHEEL CARPET FLOOR (FR-R) TOOL KIT CARPET FLOOR (RR) CEILING TRIM INTERIOR SALOON BOLT CRANE AND JACK CARSEAT (RR-L) CARPET FLOOR (FR-L) CARPET FLOOR (MID) CARSEAT (RR-R) CARPET HEAD UNIT/SIDE SKIRT REPAIR (R) ROOF REPAIR HEADLIGHT (FR-L) TAILLIGHT (RR-R) TURN LAMP (RR-R) TURN LAMP (RR-L) LICENSE PLATE DOOR REPAIR (FR-L) TAILLIGHT (RR-L) ELECTRIC MIRROR (L) BUMPER REPAIR (FR) BUMPER REPAIR (RR) FENDER REPAIR (FR-L) SIDE SKIRT REPAIR (L) FENDER REPAIR (FR-R) DOOR REPAIR (RR-R) ELECTRIC MIRROR (R) TURN LAMP (FR-L) DOOR REPAIR (RR-L) FOG LAMP (L) DOOR REPAIR (FR-R) FENDER REPAIR (RR-R) ENGINE HOOD REPAIR HEADLIGHT (FR-R) TURN LAMP (FR-R) FOG LAMP (R) FENDER REPAIR (RR-L) DOOR REPAIR (TRUNK) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
10	DG 1051 US	TOYOTA AGYA	2021	MT	1197	HITAM	RP81.000.000	BENSIN	126882	D	C	D	14 HARI KERJA	ADA 2026-07-15	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC DIDI : 0887-0550-3887// //CASHBACK SEBESAR:RP3,500,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
11	DP 1082 PE	TOYOTA INNOVA INNOVA G	2012	MT	1998	SILVER METALIK	RP79.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. PAUL 0823-1581-4593 / CS PUSAT 081188089292// MESIN BERFUNGSI, ACCU SUAK, ALARM T/A, BODY TERGORES, BAN CADANGAN T/A, HEAD UNIT T/A, SETIR IMITASI, VELG IMITASI, BAN GUNDUL, LACI DASHBOARD T/A, PLAFON KOTOR, HEADREST T/A, CONSOLE BOX T/A, SEATBELT TIDAK LENGKAP, MESIN REMBES OLI, GRILL DEPAN T/A, SPARKBOARD T/A, KNALPOT IMITASI, JOK BARIS 3 T/A//SHOCBREAKERS (FR) RADIATOR FAN COIL IGNITION SHOCBREAKERS (RR) TIRE (FR-L) CLUTCH BEARING REMOTE RIM (FR-L) MUFFLER TIRE (FR-R) RIM (RR-L) GASKET COVER HEAD BRAKE MASTER TIRE (SPARE) GASKET CYLINDER HEAD SPRING (FR) SPARK PLUG(S) BRAKE PAD (RR) ENGINE SERVICES (LIGHT) RACK STEER BRAKE PAD (FR) TIRE (RR-R) RIM (FR-R) TIRE (RR-L) FAN BELT RIM (RR-R) SPRING (RR) AIRCON EVAPORATOR BATTERY INJECTOR RIM (SPARE) CLUTCH PLATE/CARSEAT (RR-R) CARPET FLOOR (FR-R) DASHBOARD AIRCON PANEL HEADREST (M-R) HEADREST (FR-R) INTERIOR SALOON HEADREST (RR-R) CONSOLE BOX CARPET FLOOR (RR) SEATBELT (RR-L) CARPET CEILING TRIM HEADREST (RR-L) STEERING-WHEEL CEILING LAMP (FR) TOOL KIT HEADREST (FR-L) BOLT CRANE AND JACK HEAD UNIT SEATBELT (RR-R) SUNVISOR L CEILING LAMP (RR) HEADREST (M-L) CARPET FLOOR (MID) CARSEAT (RR-L) CARPET FLOOR (FR-L)/LICENSE PLATE EMBLEM WINDSHIELD WIPER RIM COVER (FR-R) DOOR REPAIR (RR-R) ANTENNA DOOR REPAIR (RR-L) ENGINE HOOD REPAIR GRILLES SIDE SKIRT REPAIR (L) FOG LAMP (R) BUMPER REPAIR (FR) TURN LAMP (RR-L) FENDER REPAIR (RR-L) RIM COVER (FR-L) MIRROR (L) SIDE SKIRT REPAIR (R) RIM COVER (RR-R) TAILLIGHT (RR-L) HEADLIGHT (FR-L) TURN LAMP (FR-R) MIRROR (R) FOG LAMP (L) DOOR REPAIR (TRUNK) FENDER REPAIR (RR-R) TAILLIGHT (RR-R) TURN LAMP (RR-R) FENDER REPAIR (FR-R) HEADLIGHT (FR-R) TURN LAMP (FR-L) RIM COVER (RR-L) BUMPER REPAIR (RR) ROOF REPAIR FENDER REPAIR (FR-L) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
12	W 1544 SS	DAIHATSU XENIA XENIA X	2017	MT	1329	PUTIH	RP61.000.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2025-06-03	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
STNK HANYA BERUPA FOTO SCAN // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. RISON 0812-4751-9346 / CS PUSAT 081188089292// BODY BARET, BUMPER BARET, VELG IMITASI, BAN IMITASI, KAKI-KAKI BUNYI, INTERIOR KUSAM, JOK SOBEK, STIR KUSAM, KARPET T/A, SPOILER T/A, LAMPU PECAH DAN KUSAM, //CLUTCH PLATE TIRE (SPARE) CLUTCH BEARING INJECTOR FAN BELT ENGINE MOUNTING RADIATOR RIM (FR-L) WHEEL BEARING (FR) SPRING (FR) SHOCBREAKERS (FR) RADIATOR FAN GASKET COVER HEAD SPARK PLUG(S) RACK STEER ENGINE SERVICES (HEAVY) FUEL PUMP TIRE (FR-R) RIM (RR-L) DISC PAD SHOCBREAKERS (RR) COIL IGNITION RIM (SPARE) RIM (RR-R) HEADER BATTERY WHEEL BEARING (RR) TIRE (RR-R) BRAKE PAD (FR) GASKET CYLINDER HEAD TIRE (RR-L) AIRCON EVAPORATOR BRAKE PAD (RR) WHEEL AXELS (RR) WHEEL AXELS (FR) SPRING (RR) BRAKE MASTER TIRE (FR-L) RIM (FR-R)/BOLT CRANE AND JACK CARSEAT (FR-R) STEERING-WHEEL CARPET FLOOR (RR) HEAD UNIT CARSEAT (FR-L) CARPET FLOOR (MID) INTERIOR SALOON CARPET FLOOR (FR-L) CARPET FLOOR (FR-R) TOOL KIT/TURN LAMP (RR-R) TAILLIGHT (RR-R) TAILLIGHT (RR-L) TURN LAMP (RR-L) HEADLIGHT (FR-L) DOOR REPAIR (FR-L) TURN LAMP (FR-R) DOOR REPAIR (FR-R) ROOF REPAIR TURN LAMP (FR-L) DOOR REPAIR (RR-R) FENDER REPAIR (FR-R) FENDER REPAIR (FR-L) BUMPER REPAIR (RR) DOOR REPAIR (TRUNK) HEADLIGHT (FR-R) BUMPER REPAIR (FR) DOOR REPAIR (RR-L) ENGINE HOOD REPAIR //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
13	DD 1749 AG	TOYOTA INNOVA INNOVA G	2017	AT	1998	HITAM METALIK	RP172.000.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2026-03-26	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
STNK HANYA BERUPA FOTO SCAN // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. PAUL 0823-1581-4593 / CS PUSAT 081188089292// MESIN BERFUNGSI, BODY TERGORES, BAN CADANGAN T/A, ALAT MOBIL T/A, SPARKBOARD T/A//SPRING (RR) SPRING (FR) WHEEL BEARING (RR) WHEEL BEARING (FR) TIRE (FR-L) RIM (SPARE) GASKET CYLINDER HEAD BRAKE PAD (RR) AIRCON EVAPORATOR SPARE KEY (IMMOBILIZER) ENGINE SERVICES (LIGHT) TIRE (RR-L) CLUTCH PLATE FAN BELT GASKET COVER HEAD BRAKE MASTER TIRE (SPARE) BRAKE PAD (FR) TIRE (FR-R) TIRE (RR-R) INJECTOR SPARK PLUG(S) CLUTCH BEARING BATTERY/TOOL KIT CARPET FLOOR (MID) CARPET FLOOR (RR) BOLT CRANE AND JACK CEILING TRIM CARPET FLOOR (FR-L) INTERIOR SALOON CARPET FLOOR (FR-R)/SIDE SKIRT REPAIR (R) FOG LAMP (R) ENGINE HOOD REPAIR FOG LAMP (L) RIM COVER (RR-L) MIRROR (R) FENDER REPAIR (FR-R) FENDER REPAIR (FR-L) FENDER REPAIR (RR-L) SIDE SKIRT REPAIR (L) RIM COVER (RR-R) FENDER REPAIR (RR-R) BUMPER REPAIR (RR) DOOR REPAIR (TRUNK) WINDSHIELD WIPER TURN LAMP (FR-R) BUMPER REPAIR (FR) TURN LAMP (FR-L) MIRROR (L) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
14	DW 1736 AT	DAIHATSU XENIA R	2018	MT	1329	MERAH METALIK	RP93.000.000	BENSIN	0	-	-	-	14 HARI KERJA	ADA 2025-06-26	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
STNK HANYA BERUPA FOTO SCAN // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. ADI 0852-9971-7153 / CS PUSAT 081188089292// MESIN BERFUNGSI, AC TIDAK DINGIN/RUSAK, BODY TERGORES, GARDAN BERMASALAH, BAN CADANGAN T/A, ALAT MOBIL T/A, VELG IMITASI, HEADREST T/A, SPARKBOARD T/A, JOK BARIS KETIGA T/A, SEATBELT TIDAK LENGKAP, CONSOLE BOX T/A, MESIN REMBES OLI//RIM (FR-L) TIRE (RR-R) TIRE (RR-L) TIRE (FR-R) REMOTE AIRCON EVAPORATOR BRAKE PAD (RR) MUFFLER RIM (RR-R) CLUTCH PLATE ENGINE SERVICES (LIGHT) TIRE (SPARE) GASKET CYLINDER HEAD CLUTCH BEARING TIRE (FR-L) SPARE KEY (IMMOBILIZER) SPRING (FR) RIM (SPARE) BRAKE MASTER RIM (RR-L) SPARK PLUG(S) INJECTOR RIM (FR-R) BRAKE PAD (FR) FAN BELT BATTERY SPRING (RR)/CARPET HEADREST (RR-L) CONSOLE BOX SEATBELT (RR-L) BOLT CRANE AND JACK CEILING LAMP (FR) CEILING TRIM HEADREST (FR-R) HEADREST (RR-R) CARPET FLOOR (RR) CARPET FLOOR (MID) TOOL KIT INTERIOR SALOON CARPET FLOOR (FR-L) HEADREST (M-L) HEADREST (M-R) SEATBELT (RR-R) CARSEAT (RR-R) CARPET FLOOR (FR-R) HEADREST (FR-L)/WINDSHIELD WIPER TAILLIGHT (RR-R) SIDE SKIRT REPAIR (R) FENDER REPAIR (RR-R) SIDE SKIRT REPAIR (L) HEADLIGHT (FR-L) TURN LAMP (RR-R) FENDER REPAIR (RR-L) RIM COVER (RR-L) DOOR REPAIR (RR-L) FOG LAMP (R) TURN LAMP (FR-R) HEADLIGHT (FR-R) FOG LAMP (L) BUMPER REPAIR (FR) TURN LAMP (FR-L) TURN LAMP (RR-L) RIM COVER (RR-R) FENDER REPAIR (FR-L) RIM COVER (FR-L) TAILLIGHT (RR-L) BUMPER REPAIR (RR) FENDER REPAIR (FR-R) DOOR REPAIR (FR-L) RIM COVER (FR-R) EMBLEM //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
15	B 1466 CMU	HONDA JAZZ GE8 1.5 S	2011	AT	1496	ABU ABU METALIK	RP74.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. FERDY 0822-4916-6365 / CS PUSAT 081188089292// MESIN BERFUNGSI, BODY TERGORES, ALARM T/A, BAN CADANGAN T/A, ALAT MOBIL T/A, MESIN REMBES OLI, VELG IMITASI, HEAD UNIT IMITASI//SPRING (FR) RIM (SPARE) SPRING (RR) GASKET COVER HEAD COIL IGNITION GASKET CYLINDER HEAD ENGINE SERVICES (LIGHT) AIRCON EVAPORATOR TIRE (RR-R) CLUTCH PLATE BRAKE PAD (RR) RACK STEER REMOTE CLUTCH BEARING INJECTOR TIRE (FR-R) TIRE (RR-L) BATTERY BRAKE MASTER TIRE (FR-L) FAN BELT TIRE (SPARE) SPARK PLUG(S) BRAKE PAD (FR)/HEAD UNIT CARPET FLOOR (FR-R) CEILING TRIM CARPET FLOOR (RR) CARPET INTERIOR SALOON BOLT CRANE AND JACK TOOL KIT CARPET FLOOR (MID) CARPET FLOOR (FR-L) CEILING LAMP (FR)/WINDSHIELD WIPER HEADLIGHT (FR-R) TURN LAMP (RR-R) HEADLIGHT (FR-L) FENDER REPAIR (RR-L) BUMPER REPAIR (RR) TAILLIGHT (RR-L) SIDE SKIRT REPAIR (L) MIRROR (R) SIDE SKIRT REPAIR (R) TURN LAMP (RR-L) TURN LAMP (FR-L) ENGINE HOOD REPAIR FENDER REPAIR (RR-R) MIRROR (L) TAILLIGHT (RR-R) FENDER REPAIR (FR-R) BUMPER REPAIR (FR) DOOR REPAIR (TRUNK) TURN LAMP (FR-R) FENDER REPAIR (FR-L) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
16	PT 1686 AD	TOYOTA RUSH S	2014	MT	1495	SILVER METALIK	RP61.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
FAKTUR BERUPA COPY LEGALISIR // UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. DEDY 0812-7358-6232 / CS PUSAT 081188089292// UNIT EX LAKA BELAKANG, BODY BARET, BUMPER BARET, BODY EX REPAINT, KACA BELAKANG PECAH, LAMPU KUSAM DAN PECAH, VELG DAN BAN IMITASI, BODY BELAKANG EX DEMPULAN, INTERIOR KUSAM, BAN GUNDUL, HEADREST TIDAK LENGKAP, MESIN REMBES OLI, NOKA KARAT, //GEAR BOX OVERHAUL ENGINE MOUNTING SPRING (RR) RIM (RR-R) RIM (SPARE) FUEL PUMP RIM (RR-L) SPRING (FR) GASKET COVER HEAD COIL IGNITION RACK STEER ENGINE SERVICES (HEAVY) MUFFLER GASKET CYLINDER HEAD TIRE (FR-R) WHEEL BEARING (FR) RADIATOR FAN RIM (FR-L) CLUTCH PLATE HEADER TIRE (RR-L) CLUTCH BEARING SHOCBREAKERS (FR) TIRE (RR-R) SHOCBREAKERS (RR) BRAKE MASTER RIM (FR-R) TIRE (FR-L) WHEEL BEARING (RR) FAN BELT TIRE (SPARE) BRAKE PAD (FR) DISC PAD RADIATOR INJECTOR SPARK PLUG(S) AIRCON EVAPORATOR BRAKE PAD (RR) BATTERY/HEADREST (M-L) TOOL KIT HEADREST (FR-L) HEADREST (M-R) HEAD UNIT CARPET FLOOR (RR) CARPET FLOOR (FR-R) CARPET FLOOR (MID) CARPET INTERIOR SALOON CARPET FLOOR (FR-L) BOLT CRANE AND JACK/FENDER REPLCE (RR-L) HEADLIGHT (FR-R) BACK GLASS DOOR REPAIR (TRUNK) HEADLIGHT (FR-L) TAILLIGHT (RR-R) BUMPER REPAIR (RR) DOOR REPAIR (FR-L) BUMPER REPAIR (FR) ENGINE HOOD REPAIR DOOR REPAIR (FR-R) TAILLIGHT (RR-L) FOG LAMP (R) TURN LAMP (FR-L) ELECTRIC MIRROR (L) RR-VENT GLASS (L) FOG LAMP (L) TURN LAMP (RR-R) DOOR REPAIR (RR-R) TURN LAMP (RR-L) DOOR REPAIR (FR-L) TURN LAMP (FR-R) ROOF REPAIR ELECTRIC MIRROR (R) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
17	DD 1437 SI	DAIHATSU XENIA R	2015	MT	1329	PUTIH	RP95.000.000	BENSIN	0	-	-	-	14 HARI KERJA	- T/A	KWT. BLANKO T/A	FAKTUR T/A	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A

LOT	NO POLISI	MERK/MODEL	TAHUN	TRANS	CC	WARNA	OPEN PRICE	BAHAN BAKAR	ODO METER	EXTER GRADE	INTER GRADE	ENGINE GRADE	BPKB	STNK	KELENGKAPAN DOKUMEN		
UNIT TIDAK DILAKUKAN PENGECEKAN OLEH TIM SMARTBID// SEBELUM MELAKUKAN PENAWARAN HARAP CEK KONDISI UNIT DAN DOKUMEN TERLEBIH DAHULU// WAJIB MENGHUBUNGI PIC DAN DATANG KE LOKASI UNTUK PENGECEKAN UNIT// UNIT DILELANG APA ADANYA PERMASALAHAN YANG TIMBUL DILUAR TANGGUNG JAWAB SMARTBID// PENGAMBILAN UNIT SLIDE H+2 DARI PELUNASAN // JIKA INGIN MENGAMBIL UNIT HARAP UNTUK KONFIRMASI DAHULU KE SMARTBID // JIKA YANG MENGAMBIL BIDDER HARAP MEMBAWA KTP ASLI // JIKA PENGAMBILAN DIWAKILKAN WAJIB MEMBAWA SURAT KUASA ASLI // LOKASI UNIT HUBUNGI BPK. AGUS 0823-4704-2525 / CS PUSAT 081188089292// MESIN BERFUNGSI, BODY TERGORES, VELG IMITASI, SETIR IMITASI, SPARKBOARD T/A, HEAD UNIT IMITASI, JOK DEPAN KANAN SOBEK, CONSOLE BOX T/A, ALAT MOBIL T/A/RACK STEER RIM (RR-L) RIM (SPARE) SPRING (RR) RIM (FR-R) GASKET CYLINDER HEAD RIM (FR-L) TIRE (SPARE) SPRING (FR) GASKET COVER HEAD RIM (RR-R) REMOTE TIRE (RR-L) CLUTCH BEARING ENGINE SERVICES (LIGHT) TIRE (FR-L) FAN BELT SPARE KEY (IMMOBILIZER) CLUTCH PLATE TIRE (FR-R) TIRE (RR-R) SPARK PLUG(S) BRAKE PAD (FR) BRAKE PAD (RR) AIRCON EVAPORATOR BRAKE MASTER BATTERY/CARPET FLOOR (FR-L) CARPET FLOOR (MID) BOLT CRANE AND JACK STEERING-WHEEL CONSOLE BOX HORN CARPET FLOOR (FR-R) CARSEAT (FR-R) CARPET FLOOR (RR) TOOL KIT INTERIOR SALOON HEAD UNIT/FENDER REPAIR (FR-R) BUMPER REPAIR (RR) TURN LAMP (RR-R) RIM COVER (FR-R) EMBLEM WINDSHIELD WIPER RIM COVER (RR-R) TURN LAMP (RR-L) FOG LAMP (R) FENDER REPAIR (RR-R) MIRROR (R) TURN LAMP (FR-L) ENGINE HOOD REPAIR FENDER REPAIR (RR-L) SIDE SKIRT REPAIR (L) TURN LAMP (FR-R) BUMPER REPAIR (FR) RIM COVER (FR-L) DOOR REPAIR (TRUNK) MIRROR (L) FENDER REPAIR (FR-L) RIM COVER (RR-L) FOG LAMP (L) ROOF REPAIR SIDE SKIRT REPAIR (R) //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
18	DP 8032 UC	HINO XZU349R	2022	MT	4009	HIJAU	RP57.000.000	SOLAR	0	E	E	F	14 HARI KERJA	ADA 2024-09-20	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC RUDAL 0821 9140 0425 // NOPOL FISIK T/A // UNIT HANYA CHASIS //CASHBACK SEBESAR:RP3,500,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
19	PY 1026 IA	TOYOTA RUSH	2010	MT	1495	MERAH METALIK	RP30.000.000	BENSIN	0	D	D	E	READY	ADA 2026-04-21	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC ANDY 082189084113 // NOPOL PADA FISIK T/A //BPKB READY HO TANGERANG // FAKTUR TIDAK JELAS BERUPA FOTO COPPY // ADA PERBEDAAN TRANSMISI PADA FISIK M/T PADA DOKUMEN STNK & NOTICE A/T // PEMENANG LELANG WAJIB TTD SURAT PERNYATAAN BERMATERAI DIKASIR // //CASHBACK SEBESAR:RP3,500,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
20	KT 8641 VG	MITSUBISHI FE 75 SHDX	2022	MT	3907	KUNING	RP118.000.000	SOLAR	0	D	E	E	14 HARI KERJA	ADA 2025-03-30	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR T/A	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC MIRZA : 0822-3357-3376 / PIC RESKI 0853-4884-2551 // //CASHBACK SEBESAR:RP3,500,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	
21	PA 1670 AZ	TOYOTA AVANZA	2013	MT	1495	PUTIH	RP61.000.000	BENSIN	312945	C	C	C	14 HARI KERJA	ADA 2022-06-08	KWT. BLANKO T/A	FAKTUR ADA	FC. KTP T/A
															KEUR ADA	SPH T/A	FORM A T/A
SEBELUM MELAKUKAN PENAWARAN UNIT PESERTA LELANG WAJIB MELAKUKAN PENGECEKAN UNIT DAN DOKUMEN TERLEBIH DAHULU // PIC GREVER PARERA 082260394365 // //CASHBACK SEBESAR:RP3,000,000 // BATAS PEMBAYARAN: 5 HARI SETELAH INVOICE RILIS																	